Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

McKenzie 3 AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

August 2010

Part I Site Identification, Location and Status Site Names and ID numbers as applicable Mine ID: 61 Map ID: N17 **CERCLIS:** NNN000908965 Navajo Abandoned Mine Land Reclamation Program: NA-0925 **Local name / Aliases:** McKenzie #3 **Chapter and local area:** Teec Nos Pos Chapter **County:** Apache **State:** Arizona **Lat/Long:** 36.905559566 N / -109.294121234 W Nearby road and highway: Highway 160 Local Post Office: Teec Nos Pos Surface Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Public lands Private Tribal Fee Land Bureau of Land Mgmt Allotment** State Fee land **Subsurface Mineral Rights:** No information on subsurface mineral rights ownership was found in the EPA/AUM Database. **Claim and operator information:** The mine site surface land status is classified as Tribal Trust Land. No other historical ownership / lease information was identified in the EPA/AUM database. Number of residential structures within 200 feet of mine: None

Estimated volume of mine waste onsite: 110 yd³

Part II Summary of radiological readings

Highest gamma radiation measurement:

304,228 counts per minute (cpm)

Describe any other radiological measurements:


A total of 4,915 gamma radiation measurements were collected from the mine site, ranging from 5,078 cpm to 304,228 cpm. Measurements collected in the vicinity of the waste debris were found at levels up to approximately 13,000 cpm, in the drainage below the waste debris up to approximately 50,000 cpm, and at the reclamation caps at levels up to approximately 13,000 cpm. The measurements are represented in Figures 1 and 2.

Background Locations #1 10,304 cpm

Average background = 10,304 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 4915

 Minimum:
 5078,00000

 Maximum:
 304228,00000

 Sum:
 65341919,00000

 Mean:
 13294,38840

 Median:
 10826,00000

 Standard Deviation:
 16838,45357

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

NAMLRP Project Number: NA-0925, NA-0903

NAMLRP Mine features: 3 Rim Strip / Pits, 1 Portal

The following information was obtained from field observations collected during the 2010 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed	reclamation	work and	ctatuc.
COUNCI VCU	i cciainauvii	wui K anu	Status.

Adits

None

Waste Piles

Waste pile at NW part of site, 25' x 20' x 6', drainage running adjacent to pile to S

Pits

None

Shafts

None

Other Debris and Mine Features

3 reclamation caps in center of site, totaling 150' x 150' x 3': SE cap 125' x 50' x 3'; SW cap 25' x 35' x 2'; 2 caps at W boundary: 25' x 15' x 2'; 50' x 20' x 3'

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: Windmill well immediately S of site

0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

McKenzie 3 mine consists of an area of 75,271.28 m². The mine was identified as being operational from 1955 to 1956. While operational, the mine had a total reported production volume of 504 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Site Name(s): McKenzie 3 **Chapter:** Teec Nos Pos

Decision Criteria

Is there an unreclaimed waste pile at the site? Yes

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? 0.25 mi

Is there a reclamation cap or sealed adit in place at the site? Yes

Is the cap/seal functionally intact? Yes

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? 300 ft

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

Reclamation caps; unreclaimed waste rock

Part VI Photos



Photo 1. McKenzie 3 site



Photo 2. McKenzie 3 site, reclaimed area



Photo 3. McKenzie 3 site, reclaimed area and unreclaimed waste



Photo 4. McKenzie 3 site, reclaimed area and unreclaimed waste



Photo 5. McKenzie 3 site, reclaimed area



Photo 6. McKenzie 3 site, reclaimed area



Photo 7. McKenzie 3 site, windmill well S of site




Photo 8. McKenzie 3 site, trough S of site

Part VII Contacts Reports and Information

Name:	<u>Stanley Edison</u> (928) 871-6861		
	Eugene Esplain (928) 871-7331		
Title or of	ficial role (if any) Navajo EPA Superfund Program		
Address_	PO Box 2946, Window Rock, AZ 86515		
Information	on provided <u>Lead Regulatory Agency</u>		
Name			
Title or of	ficial role (if any)		
Telephone number			
Information	on provided		
Name		_	
Title or of	ficial role (if any)		
Telephone			
1	number		
	on provided		
Informatio			
Information Name	on provided		
Information Name	ficial role (if any)		
Name Title or of	on provided ficial role (if any)	_	

Figure 1 - Gamma Radiation Measurements, Above Two Times Background McKenzie 3 (61) Teec Nos Pos Chapter, Navajo Nation



Gamma Radiation Measurements

- < 2X Backgound
- > 2X Background

Gamma survey conducted 06/2010

Measured as counts per minute (cpm)

General Direction Down-Slope



Observed Well



Observed Waste Pile




Observed Reclamation Cap

Mine Claim Boundaries



Average background = 10,304 cpm

Figure 2 - Gamma Radiation Measurements McKenzie 3 (61) Teec Nos Pos Chapter, Navajo Nation



Legend

Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000



Observed Reclamation Cap

Gamma survey conducted 06/2010 Measured as counts per minute (cpm)

Average background 10,304 cpm

